

# Material Test Report

**Report Number:** CP20127-2B  
**Issue Number:** 1  
**Date Issued:** 21/07/2020  
**Client:** Tharwa Sands  
PO Box 428, Kippax ACT 2615  
**Project Number:** CP20127  
**Project Name:** Quality Control Testing  
**Project Location:** Parkwood Road, Wallaroo, N.S.W  
**Work Request:** 508  
**Sample Number:** CS508A  
**Date Sampled:** 16/07/2020  
**Dates Tested:** 16/07/2020 - 21/07/2020  
**Sampling Method:** AS 1289.1.2.1 6.2 - Sampling from stockpiles  
**Preparation Method:** AS 1289.1.1 - Sampling and preparation of soils  
**Site Selection:** Selected by Client  
**Sample Location:** Bedding Sand Ginninderra Quarry, Depth: Stockpile



**J & A Geotech  
Testing Pty Ltd**

Canberra Laboratory  
Unit 2, 25 Dacre Street Mitchell ACT 2911  
Phone: (02) 6255 5363  
Email: scott.miller@jageotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



Approved Signatory: Scott Miller  
Lab Manager  
NATA Accredited Laboratory Number: 19979

## Particle Size Distribution (AS1141.11.1)

Sample Washing	Sample was Washed		
	Passed %	Passing Limits	
Sieve			
9.5 mm	100		
6.7 mm	100		
4.75 mm	99		
2.36 mm	95		
1.18 mm	72		
0.6 mm	26		
0.425 mm	10		
0.3 mm	5		
0.15 mm	2		
0.075 mm	2		