

Material Test Report

Report Number: CP20127-2B
Issue Number: 1
Date Issued: 21/07/2020
Client: Tharwa Sands
PO Box 428, Kippax ACT 2615
Project Number: CP20127
Project Name: Quality Control Testing
Project Location: Parkwood Road, Wallaroo, N.S.W
Work Request: 508
Dates Tested: 16/07/2020 - 21/07/2020



**J & A Geotech
Testing Pty Ltd**

Canberra Laboratory
Unit 2, 25 Dacre Street Mitchell ACT 2911
Phone: (02) 6255 5363
Email: scott.miller@jageotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



Approved Signatory: Scott Miller
Lab Manager

NATA Accredited Laboratory Number: 19979

pH Value of Soil AS 1289 4.3.1

Sample Number	Borehole No	Depth (m)	pH	Remarks
CS508A	Bedding Sand Ginninderra Quarry	**	6.3	**
CS508B	Washed River Sand Ginninderra Quarry	**	6.6	**