

Material Test Report

Report Number: CP20127-2B
Issue Number: 1
Date Issued: 21/07/2020
Client: Tharwa Sands
PO Box 428, Kippax ACT 2615
Project Number: CP20127
Project Name: Quality Control Testing
Project Location: Parkwood Road, Wallaroo, N.S.W
Work Request: 508
Sample Number: CS508B
Date Sampled: 16/07/2020
Dates Tested: 16/07/2020 - 21/07/2020
Sampling Method: AS 1289.1.2.1 6.2 - Sampling from stockpiles
Preparation Method: AS 1289.1.1 - Sampling and preparation of soils
Site Selection: Selected by Client
Sample Location: Washed River Sand Ginninderra Quarry, Depth: Stockpile



**J & A Geotech
Testing Pty Ltd**

Canberra Laboratory
Unit 2, 25 Dacre Street Mitchell ACT 2911
Phone: (02) 6255 5363
Email: scott.miller@jageotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



Approved Signatory: Scott Miller
Lab Manager
NATA Accredited Laboratory Number: 19979

Particle Size Distribution (AS1141.11.1)

Sample Washing	Sample was Washed		
	Passed %	Passing Limits	
Sieve			
13.2 mm	100		
9.5 mm	99		
6.7 mm	98		
4.75 mm	98		
2.36 mm	94		
1.18 mm	68		
0.6 mm	25		
0.425 mm	11		
0.3 mm	6		
0.15 mm	2		
0.075 mm	2		